

ITEM Professional Development Center		287	UNITS SF	UNIT COUNT 3000	\$	TOTAL 861,00
Learning Resource Center	\$ \$	314	SF	3000	•	942,00
SUBTOT					\$	1,803,00
Continger TO	ncy: TAL	20%			\$ \$	360,66 2,163,66
					Ψ	2,100,0
RECONFIGURE CLASSROOM BLDG. 200 TO ADM		ENT SERV ST/SF	/ICES UNITS	UNIT COUNT		TOTAL
Administrative & Counselling offices	\$	291	SF	8800	\$	2,560,8
Classrooms	\$	255	SF	1680	\$	428,4
Nurse/Clinic	\$	295	SF	1680	\$	495,6
ASB	\$	295	SF	1920		566,4
SUBTOT		200/			\$	4,051,2
Continger TO	TAL	20%			\$	810,2 4,861,4
RECONFIGURE BLDG. 300 CLASSROOMS TO SCI	IFNCF I A	BS/RENO	VATE EXIS	TING I ABS		
ITEM		ST/SF	UNITS	UNIT COUNT		TOTAL
Renovate Existing Science Labs	\$	296 469	SF	6400	<u>.</u>	1,894,4
Reconfigure Classrooms to Science Labs SUBTOT	<u></u> ΓΔΙ·	468	SF	6500	\$ \$	3,042,0 4,936,4
Continger		20%			\$ \$	987,2
	TAL	2070			\$	5,923,6
LIGHT MODERNIZATION OF CLASSROOM BLDGS	S. 400					
ITEM	CC	ST/SF	UNITS	UNIT COUNT	Φ.	TOTAL
Bldg. 400 Modernization SUBTOT	<u>\$</u> ΓΔΙ·	164	SF	12600	\$ \$	2,066,4 2,066,4
Continger		20%			φ \$	2,000,4 413,2
	TAL	2070			\$	2,479,6
						, ,
MODERNIZE ROBOTICS CLASSROOM BLDG.						
ITEM		ST/SF	UNITS	UNIT COUNT	Φ.	TOTAL
4 Robotics Labs Site Work	\$ \$	285 25	SF LS	9200 15500	-	2,622,0 387,5
SUBTOT	Ψ ΓAL:		LO	10000	\$	3,009,5
Continger		20%			\$	601,9
TO	TAL				\$	3,611,4
					Ψ	3,011,4
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI		NST/SE	LIMITS		Ψ	
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI	CC	ST/SF 239	UNITS SF	UNIT COUNT		TOTAL
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI		ST/SF 239 25	UNITS SF SF	UNIT COUNT 2000 15000	\$	TOTAL 478,0
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs.	\$ \$	239	SF	2000	\$	TOTAL 478,0 375,0
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs. Site Work SUBTOT Continger	\$ \$ \$ FAL: ncy:	239	SF	2000	\$ \$ \$	TOTAL 478,0 375,0 853,0 170,6
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs. Site Work SUBTOT Continger	CC \$ \$ FAL: ncy: TAL	239 25 20%	SF SF	2000 15000	\$ \$	TOTAL 478,0 375,0 853,0 170,6
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO	CC \$ \$ FAL: ncy: TAL	239 25 20% FTER SCH	SF SF	2000 15000 GRAMS	\$ \$ \$	TOTAL 478,0 375,0 853,0 170,6 1,023,6
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO: RECONFIGURE EXISTING ADMIN. BLDG. TO LIBR	CC \$ \$ FAL: ncy: TAL	239 25 20%	SF SF	2000 15000	\$ \$ \$ \$	TOTAL 478,0 375,0 853,0 170,6 1,023,6
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO RECONFIGURE EXISTING ADMIN. BLDG. TO LIBRATEM Library Classrooms	CC \$ \$ FAL: ncy: TAL CC \$ \$	239 25 20% FTER SCH OST/SF	SF SF IOOL PROC	2000 15000 GRAMS UNIT COUNT	\$ \$ \$ \$	TOTAL 478,0 375,0 853,0 170,6 1,023,6 TOTAL 565,2 459,0
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO: RECONFIGURE EXISTING ADMIN. BLDG. TO LIBR ITEM Library Classrooms SUBTOT	CC \$ \$ FAL: ncy: TAL CC \$ \$ \$	239 25 20% FTER SCH ST/SF 314 255	SF SF UNITS SF	2000 15000 ERAMS UNIT COUNT 1800	\$ \$ \$ \$ \$ \$ \$ \$ \$	TOTAL 478,0 375,0 853,0 170,6 1,023,6 TOTAL 565,2 459,0 1,024,2
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO: RECONFIGURE EXISTING ADMIN. BLDG. TO LIBR ITEM Library Classrooms SUBTOT Continger	CC \$ \$ FAL: ncy: TAL CC \$ \$ FAL: ncy:	239 25 20% FTER SCH ST/SF 314	SF SF UNITS SF	2000 15000 ERAMS UNIT COUNT 1800	\$ \$ \$ \$ \$ \$ \$ \$ \$	TOTAL 478,0 375,0 853,0 170,6 1,023,6 TOTAL 565,2 459,0 1,024,2 204,8
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO: RECONFIGURE EXISTING ADMIN. BLDG. TO LIBR ITEM Library Classrooms SUBTOT Continger	CC \$ \$ FAL: ncy: TAL CC \$ \$ \$	239 25 20% FTER SCH ST/SF 314 255	SF SF UNITS SF	2000 15000 ERAMS UNIT COUNT 1800	\$ \$ \$ \$ \$ \$ \$ \$ \$	TOTAL 478,0 375,0 853,0 170,6 1,023,6 TOTAL 565,2 459,0 1,024,2 204,8
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO: RECONFIGURE EXISTING ADMIN. BLDG. TO LIBR ITEM Library Classrooms SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS	CC \$ FAL: ncy: TAL RARY & A CC \$ \$ FAL: ncy: TAL	239 25 20% FTER SCH ST/SF 314 255 20%	SF SF UNITS SF SF	2000 15000 ERAMS UNIT COUNT 1800 1800	\$ \$ \$ \$ \$ \$ \$ \$ \$	TOTAL 478,0 375,0 853,0 170,6 1,023,6 TOTAL 565,2 459,0 1,024,2 204,8 1,229,0
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO: RECONFIGURE EXISTING ADMIN. BLDG. TO LIBR ITEM Library Classrooms SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM	CC \$ FAL: ncy: TAL RARY & A CC \$ \$ FAL: ncy: TAL	239 25 20% FTER SCH ST/SF 314 255	SF SF UNITS SF	2000 15000 ERAMS UNIT COUNT 1800	\$\$ \$\$ \$\$ \$\$	TOTAL 478,0 375,0 853,0 170,6 1,023,6 TOTAL 565,2 459,0 1,024,2 204,8 1,229,0 TOTAL
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO: RECONFIGURE EXISTING ADMIN. BLDG. TO LIBR ITEM Library Classrooms SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM	CC \$ \$ FAL: ncy: TAL \$ \$ FAL: ncy: TAL S. 500	239 25 20% FTER SCH ST/SF 314 255 20%	SF SF UNITS SF SF UNITS	2000 15000 SRAMS UNIT COUNT 1800 1800 UNIT COUNT	\$\$ \$\$ \$\$ \$\$	TOTAL 478,0 375,0 853,0 170,6 1,023,6 TOTAL 565,2 459,0 1,024,2 204,8 1,229,0 TOTAL 885,6
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTED ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO: RECONFIGURE EXISTING ADMIN. BLDG. TO LIBRATED Library Classrooms SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 500 Modernization SUBTOT Continger Continger	FAL: ncy: TAL S. 500 CC \$ FAL: ncy: TAL	239 25 20% FTER SCH ST/SF 314 255 20%	SF SF UNITS SF SF UNITS	2000 15000 SRAMS UNIT COUNT 1800 1800 UNIT COUNT	\$\$ \$ \$\$	TOTAL 478,0 375,0 853,0 170,6 1,023,6 TOTAL 565,2 459,0 1,024,2 204,8 1,229,0 TOTAL 885,6 885,6 177,1
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTED ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO: RECONFIGURE EXISTING ADMIN. BLDG. TO LIBRATED Library Classrooms SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 500 Modernization SUBTOT Continger Continger	SARY & A CC \$ FAL: RARY & A CC \$ FAL: CC \$ CC \$ CC \$ TAL CC \$ FAL: CC \$ FAL:	239 25 20% FTER SCH ST/SF 314 255 20%	SF SF UNITS SF SF UNITS	2000 15000 SRAMS UNIT COUNT 1800 1800 UNIT COUNT	\$\$ \$\$ \$\$ \$\$	TOTAL 478,0 375,0 853,0 170,6 1,023,6 TOTAL 565,2 459,0 1,024,2 204,8 1,229,0 TOTAL 885,6 885,6 177,1
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO: RECONFIGURE EXISTING ADMIN. BLDG. TO LIBR ITEM Library Classrooms SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 500 Modernization SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 500 Modernization	FAL: ncy: TAL S. 500 CC \$ FAL: ncy: TAL S. 500 CC TAL S. 600	239 25 20% FTER SCH ST/SF 314 255 20% ST/SF 164 20%	SF SF UNITS SF UNITS SF	2000 15000 SRAMS UNIT COUNT 1800 1800 UNIT COUNT 5400	\$\$ \$ \$\$	TOTAL 478,0 375,0 853,0 170,6 1,023,6 TOTAL 565,2 459,0 1,024,2 204,8 1,229,0 TOTAL 885,6 177,1 1,062,7
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO RECONFIGURE EXISTING ADMIN. BLDG. TO LIBR ITEM Library Classrooms SUBTOT Continger TO LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 500 Modernization SUBTOT Continger TO LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 500 Modernization	FAL: ncy: TAL S. 500 CC \$ FAL: ncy: TAL S. 500 CC TAL S. 600	239 25 20% FTER SCH ST/SF 314 255 20% ST/SF 164 20%	SF SF UNITS SF SF UNITS UNITS	2000 15000 SRAMS UNIT COUNT 1800 1800 UNIT COUNT 5400 UNIT COUNT	\$\$ \$ \$\$\$\$\$\$\$\$\$\$\$\$\$	TOTAL 478,0 375,0 853,0 170,6 1,023,6 TOTAL 565,2 459,0 1,024,2 204,8 1,229,0 TOTAL 885,6 177,1 1,062,7
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO RECONFIGURE EXISTING ADMIN. BLDG. TO LIBR ITEM Library Classrooms SUBTOT Continger TO LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 500 Modernization SUBTOT Continger TO LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 500 Modernization	### CC \$ \$ \$ \$ \$ \$ \$ \$ \$	239 25 20% FTER SCH ST/SF 314 255 20% ST/SF 164 20%	SF SF UNITS SF UNITS SF	2000 15000 SRAMS UNIT COUNT 1800 1800 UNIT COUNT 5400	\$\$ \$ \$\$	TOTAL 478,0 375,0 853,0 170,6 1,023,6 TOTAL 565,2 459,0 1,024,2 204,8 1,229,0 TOTAL 885,6 177,1 1,062,7 TOTAL 885,6
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO: RECONFIGURE EXISTING ADMIN. BLDG. TO LIBR ITEM Library Classrooms SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 500 Modernization SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 600 Modernization	### CC \$ \$ \$ \$ \$ \$ \$ \$ \$	239 25 20% FTER SCH ST/SF 314 255 20% ST/SF 164 20%	SF SF UNITS SF SF UNITS UNITS	2000 15000 SRAMS UNIT COUNT 1800 1800 UNIT COUNT 5400 UNIT COUNT	\$\$ \$ \$\$\$\$\$\$\$\$\$\$\$\$\$	TOTAL 478,0 375,0 853,0 170,6 1,023,6 TOTAL 565,2 459,0 1,024,2 204,8 1,229,0 TOTAL 885,6 177,1 1,062,7 TOTAL 885,6 885,6
RECONFIGURE 800 BLDG. TO GROUNDS/MAINT ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO: RECONFIGURE EXISTING ADMIN. BLDG. TO LIBR ITEM Library Classrooms SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 500 Modernization SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 500 Modernization SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 600 Modernization SUBTOT Continger TO: SUBTOT Continger	### CC \$ \$ \$ \$ \$ \$ \$ \$ \$	239 25 20% FTER SCH ST/SF 314 255 20% ST/SF 164 20%	SF SF UNITS SF SF UNITS UNITS	2000 15000 SRAMS UNIT COUNT 1800 1800 UNIT COUNT 5400 UNIT COUNT	\$\$ \$ \$\$\$\$\$\$\$\$\$\$\$\$\$	TOTAL 478,0 375,0 853,0 170,6 1,023,6 TOTAL 565,2 459,0 1,024,2 204,8 1,229,0 TOTAL 885,6 177,1 1,062,7 TOTAL 885,6 177,1 1,07,1
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO: RECONFIGURE EXISTING ADMIN. BLDG. TO LIBR ITEM Library Classrooms SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 500 Modernization SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 600 Modernization SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 600 Modernization SUBTOT Continger TO:	FAL: ncy: TAL S. 500 CC \$ FAL: ncy: TAL S. 600 CC \$ FAL: ncy: TAL	239 25 20% FTER SCH ST/SF 314 255 20% ST/SF 164 20%	SF SF UNITS SF SF UNITS UNITS	2000 15000 SRAMS UNIT COUNT 1800 1800 UNIT COUNT 5400 UNIT COUNT	\$\$ \$\$\$ \$	TOTAL 478,0 375,0 853,0 170,6 1,023,6 TOTAL 565,2 459,0 1,024,2 204,8 1,229,0 TOTAL 885,6 177,1 1,062,7
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO: RECONFIGURE EXISTING ADMIN. BLDG. TO LIBR ITEM Library Classrooms SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 500 Modernization SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 600 Modernization SUBTOT Continger TO: RECONFIGURE LIBRARY TO BAND/MARIACHI BL	FAL: ncy: TAL S. 500 CC \$ TAL: ncy: TAL S. 600 CC \$ TAL: ncy: TAL TAL TAL TAL TAL TAL TAL	239 25 20% FTER SCH ST/SF 314 255 20% ST/SF 164 20%	SF SF UNITS SF SF UNITS UNITS	2000 15000 SRAMS UNIT COUNT 1800 1800 UNIT COUNT 5400 UNIT COUNT	\$\$ \$\$\$ \$	TOTAL 478,0 375,0 853,0 170,6 1,023,6 TOTAL 565,2 459,0 1,024,2 204,8 1,229,0 TOTAL 885,6 177,1 1,062,7 TOTAL 885,6 177,1 1,07,1
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO: RECONFIGURE EXISTING ADMIN. BLDG. TO LIBR ITEM Library Classrooms SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 500 Modernization SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 600 Modernization SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 600 Modernization SUBTOT Continger TO: RECONFIGURE LIBRARY TO BAND/MARIACHI BL ITEM 2 Band Classrooms	FAL: ncy: TAL S. 500 CC \$ TAL: ncy: TAL S. 600 CC \$ TAL: ncy: TAL TAL TAL TAL TAL TAL TAL	239 25 20% FTER SCH ST/SF 314 255 20% ST/SF 164 20% ST/SF 164 20%	UNITS SF UNITS SF UNITS SF	2000 15000 BRAMS UNIT COUNT 1800 1800 1800 UNIT COUNT 5400 UNIT COUNT 5400	\$\$ \$\$\$ \$	TOTAL 478,0 375,0 853,0 170,6 1,023,6 TOTAL 565,2 459,0 1,024,2 204,8 1,229,0 TOTAL 885,6 177,1 1,062,7 TOTAL 885,6 177,1 1,062,7
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO: RECONFIGURE EXISTING ADMIN. BLDG. TO LIBR ITEM Library Classrooms SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 500 Modernization SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 600 Modernization SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 600 Modernization SUBTOT Continger TO: RECONFIGURE LIBRARY TO BAND/MARIACHI BL ITEM 2 Band Classrooms Site Work (Semi-temporary until Quad constr.)	FAL: ncy: TAL S. 500 CC \$ TAL: ncy: TAL S. 600 CC \$ TAL: ncy: TAL CC CC CC CC CC CC CC CC CC	239 25 20% FTER SCH ST/SF 314 255 20% ST/SF 164 20% ST/SF 164 20%	UNITS SF UNITS SF SF SF	2000 15000 BRAMS UNIT COUNT 1800 1800 1800 UNIT COUNT 5400 UNIT COUNT 4775 6000	\$\$ \$\$\$ \$	TOTAL 478,0 375,0 853,0 170,6 1,023,6 TOTAL 565,2 459,0 1,024,2 204,8 1,229,0 TOTAL 885,6 177,1 1,062,7 TOTAL 885,6 177,1 1,062,7
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO: RECONFIGURE EXISTING ADMIN. BLDG. TO LIBRA ITEM Library Classrooms SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 500 Modernization SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 600 Modernization SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 600 Modernization SUBTOT Continger TO: RECONFIGURE LIBRARY TO BAND/MARIACHI BL ITEM 2 Band Classrooms Site Work (Semi-temporary until Quad constr.) Site Demolition	### CC \$ \$ \$ \$ \$ \$ \$ \$ \$	239 25 20% FTER SCH ST/SF 314 255 20% ST/SF 164 20% ST/SF 164 20%	UNITS SF UNITS SF UNITS SF	2000 15000 BRAMS UNIT COUNT 1800 1800 1800 UNIT COUNT 5400 UNIT COUNT 5400	\$\$ \$\$\$ \$	TOTAL 478,0 375,0 853,0 170,6 1,023,6 TOTAL 565,2 459,0 1,024,2 204,8 1,229,0 TOTAL 885,6 177,1 1,062,7 TOTAL 1,742,8 120,0 30,0
RECONFIGURE 800 BLDG. TO GROUNDS/MAINTI ITEM Reconfigure two bldgs. Site Work SUBTOT Continger TO: RECONFIGURE EXISTING ADMIN. BLDG. TO LIBR ITEM Library Classrooms SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 500 Modernization SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 600 Modernization SUBTOT Continger TO: LIGHT MODERNIZATION OF CLASSROOM BLDGS ITEM Bldg. 600 Modernization SUBTOT Continger	### CC \$ \$ \$ \$ \$ \$ \$ \$ \$	239 25 20% FTER SCH ST/SF 314 255 20% ST/SF 164 20% ST/SF 164 20%	UNITS SF UNITS SF SF SF	2000 15000 BRAMS UNIT COUNT 1800 1800 1800 UNIT COUNT 5400 UNIT COUNT 4775 6000	\$\$ \$\$\$ \$	TOTAL 478,00 375,00 853,00 170,60 1,023,60 TOTAL 565,20 459,00 1,024,20 204,84 1,229,04 TOTAL 885,60 177,12 1,062,72 TOTAL 885,60 177,12 1,062,72

	ITEM		\mathcal{C}	COST/SF
	Seat wall planters w/ tree		\$	10,000
	Paving & landscaping		\$	25
	Elevated Platform & Shade Structure		\$	350,000
	Steel fencing/gates		\$	75 3 500 000
	Site Infrastructure Improvements Paving and landscaping		\$ \$	3,500,000 25
	<u>. aviiig aira lairaeeapiiig</u>	SUBTOTAL:	Ψ	
		Contingency: TOTAL		20%
	MODERNIZE GYMNASIUM			00T/0F
	ITEM Gymnasium		\$	OST/SF 292
	Modernize Restrooms		\$	516
	Fitness Center		\$	292
	Offices/storage		\$	291
		SUBTOTAL:		000/
		Contingency: TOTAL		20%
1	MODERNIZE THEATER BLDG.		_	NOCT/OF
	ITEM Modernize Theater		\$	OST/SF 498
	Site Work		\$	25
		SUBTOTAL:		
		Contingency: TOTAL		20%
)	NEW 5 CLASSROOM+ASB/NUTRITION ITEM	I SERVICE BLDO	Ò	OST/SF
	Standard Classrooms Special Ed. Classroom		\$ \$	287 297
	Hygiene Space		\$	527
	ASB		\$	287
	Nutrition Services Bldg.		\$	515
	3 Temporary Relocatable Team Rooms Demolish 700 wing		\$ \$	177 17
	Demonstr 700 wing	SUBTOTAL:	φ	17
		Contingency: TOTAL		20%
)	NEW 9 CLASSROOM BLDG.			
	ITEM Standard Classrooms		\$	287 287
	Special Ed. Classroom		Ψ \$	297
	Hygiene Space		\$	527
	Demolish 900 wing		\$	17
	Site Work	CHDTOTAL	\$	25
		SUBTOTAL: Contingency: TOTAL		20%
Q	NEW GYMNASIUM/WRESTLING/DANC	E/LOCKERS (FU		IRE BOND
	Gymnasium		\$	310
	Shower/Locker Rooms		\$	420
	Dance/Wrestling Rooms		\$	310
	New Team Rooms		\$	420
	Relocate Tennis Courts	SUBTOTAL: Contingency:	\$	75,000 20%
		TOTAL		
R	RELOCATE TENNIS COURTS		_	OOT/OF
_	Relocate 8 Tennis Courts		<u>C</u> \$	OST/SF 75,000
	radiodate o Tellillo Oddito		Ψ	

ITEM		C	OST/SF	UNITS	UNIT COUNT		TOTAL
Seat wall planters w/ tree		\$	10,000	EA	37	\$	370,00
Paving & landscaping		\$	25	SF	122000	\$	3,050,00
Elevated Platform & Shade Structure		\$	350,000	LS	1	\$	350,00
Steel fencing/gates		\$	75	LF	1600	\$	120,00
Site Infrastructure Improvements		\$ 3	3,500,000	LS	1	\$	3,500,00
Paving and landscaping		\$	25	LS	30000	\$	750,00
	SUBTOTAL:	·				\$	8,140,00
	Contingency:		20%			\$	1,628,00
	TOTAL					\$	9,768,00
MODERNIZE GYMNASIUM							
ITEM		C	OST/SF	UNITS	UNIT COUNT		TOTAL
Gymnasium		\$	292	SF	11250	\$	3,285,00
Modernize Restrooms		\$	516	SF	400	\$	206,40
Fitness Center		\$	292	SF	8200	\$	2,394,40
Offices/storage		\$	291	SF	1600	\$	465,60
	SUBTOTAL:	·				\$	6,351,40
	Contingency:		20%			\$	1,270,28
	TOTAL					\$	7,621,68
MODERNIZE THEATER BLDG.							
ITEM		C	OST/SF	UNITS	UNIT COUNT		TOTAL
Modernize Theater		\$	498	SF	9200	\$	4,581,60
Site Work		\$	25	SF	15500	\$	387,50
	SUBTOTAL:					\$	4,969,10
	Contingency:		20%			\$	993,82
	TOTAL					\$	5,962,92
NEW 5 CLASSROOM+ASB/NUTRITION	SERVICE BLDO	3. (F	UTURE BO	ND)			
ITEM		C	OST/SF	UNITS	UNIT COUNT		TOTAL
Standard Classrooms		\$	287	SF	3840	\$	1,102,08
Special Ed. Classroom		\$	297	SF	960	\$	285,12
Hygiene Space		\$	527	SF	225	\$	118,57
ASB		\$	287	SF	1170	\$	335,79
Mutrition Convious Plda		\$	515	SF	2560	\$	1,318,40
Multillon Services blug.		\$	177	SF	3000	\$	531,00
G		Ψ		CE	20750	Ф	352,75
3 Temporary Relocatable Team Rooms		\$	17	SF	20130	Ψ	
Nutrition Services Bldg. 3 Temporary Relocatable Team Rooms Demolish 700 wing	SUBTOTAL:		17	<u> </u>	20730	φ \$	4,043,71
3 Temporary Relocatable Team Rooms			17 20%	<u> 5</u> F	20730	-:-	, ,
3 Temporary Relocatable Team Rooms	SUBTOTAL: Contingency: TOTAL			<u> 5r</u>	20730	-:-	808,74
3 Temporary Relocatable Team Rooms Demolish 700 wing	Contingency:			<u>5F</u>	20730	\$	808,74
3 Temporary Relocatable Team Rooms Demolish 700 wing NEW 9 CLASSROOM BLDG.	Contingency:	\$		UNITS	UNIT COUNT	\$	808,74
3 Temporary Relocatable Team Rooms	Contingency:	\$	20%			\$ \$ \$	4,043,71 808,74 4,852,45 TOTAL 2,204,16
3 Temporary Relocatable Team Rooms Demolish 700 wing NEW 9 CLASSROOM BLDG. ITEM	Contingency:	\$ C(20% OST/SF	UNITS	UNIT COUNT	\$ \$ \$	808,74 4,852,45 TOTAL
3 Temporary Relocatable Team Rooms Demolish 700 wing NEW 9 CLASSROOM BLDG. ITEM Standard Classrooms	Contingency:	\$ C(20% OST/SF 287	UNITS SF	UNIT COUNT 7680	\$ \$ \$ \$ \$	808,74 4,852,45 TOTAL 2,204,16



Sweetwater Union High School District Southwest High School DRAFT

TOTAL HARD CONSTRUCTION COST, ALL PROJECTS	\$ 82,821,564
HAZARDOUS MATERIALS ABATEMENT (10% OF CONSTRUCTION COST)	\$ 8,282,156
SOFT COSTS (30% OF CONSTRUCTION COST)	\$ 24,846,469
FURNITURE, FIXTURES, AND EQUIPMENT (7% OF CONSTRUCTION COST)	\$ 5,797,509
TOTAL ESTIMATED PROJECT COST, JANUARY 2017	\$ 121,747,699
ESTIMATED PROJECT COST ESCALATED TO JANUARY 2019	\$ 134,226,838

ASSUMPTIONS:

Hazardous materials surveys and abatement add 10% increase to construction costs Soft costs are 30% of construction cost. Soft costs include:

Design fees Management costs Testing & inspection Topographic and utilities surveying Geotechnical studies DSA plan check fees

EXCLUSIONS:

29135 \$

5500

UNIT COUNT

UNIT COUNT

UNIT COUNT

1 \$

5000 \$

728,375

3,688,980

4,426,776

5,550,000

1,110,000

737,796

Escalation beyond January 2019 Relocation costs

Interim housing costs (unless specifically identified in project cost)

THE ESTIMATE IS DEVELOPED IN EXCEL, EXPORTED AS A PDF INTO INDESIGN. FORMAT THIS PAGE WITH 3 EQUAL WIDTH COLUMNS IN WHICH TO PLACE PAGES. THE FONT SIZE SHOULD BE 11 PT. IN THE EXCEL FILE WHICH, WHEN IMPORTED INTO INDESIGN, WILL APPROXIMATE A 7 PT. FONT SIZE ON AN 11" X 17" PAGE SIZE.

TOTAL 6,660,000 RELOCATE SOFTBALL FIELD, IMPROVE SITE AT BASEBALL FIELD TOTAL **UNIT COUNT** 550,000 \$ 550,000 LS Relocate Softball Field 1 \$ Upgrade Site & Paving around Baseball/Softball Fields 45000 \$ 25 1,125,000 SUBTOTAL: 1,675,000 **Contingency:** 20% 335,000 **TOTAL** 2,010,000

COST/SF

\$ 3,500,000

20%

410

20%

SUBTOTAL:

TOTAL

Contingency:

SUBTOTAL:

Contingency:

NEW TRACK & FIELD, BLEACHERS

All-weather track & synthetic field

New Bleachers & Press Box

SF

UNITS

UNITS

UNITS

LS

seat

Preliminary Conceptual Master Plan Estimate of Project Costs

March 2017

